



Jeffrey C. May

May Indoor Air Investigations LLC
Tyngsborough, MA

Moisture and Leak
Investigations



© 2025 J. May

Tools and Instruments

Typical Inspection Equipment:

Screwdrivers, needle-nose pliers, flashlight, camera, etc.



Mirror

**Flame mirror
with mirror
glass doubled
taped**



Wash bottle

NO HOSING!!!!!!

May Indoor Air Investigations



**Syringe or
dropper**



Top of pipe

Why you need a mirror



Bottom of pipe

MOISTURE AND LEAK INVESTIGATIONS

Patterns of liquid flow


Patterns of condensation

Relative humidity (RH)

Dew point


Measuring moisture content of wood

Case studies of moisture and health problems in homes



**Observation and pattern
recognition are important parts of
moisture diagnostics.**

May Indoor Air Investigations



Masonite siding removed

Masonry Patterns

Water flows through the limestone joints.
Efflorescence/freeze/thaw damage



Water moves soiling

This image shows a close-up of a stone wall, likely made of limestone, with visible horizontal and vertical joints. A dark, horizontal stain or soiling is visible across the middle of the frame, suggesting water has moved through the joints and deposited minerals. The stone has a weathered, greyish-brown appearance.



Photo taken just
after rain started

This image shows a stone archway with a dark, horizontal stain across its surface. The stain is more prominent on the left side of the arch. The stone is light-colored and shows signs of weathering. A metal fence is visible in the background to the left of the arch.

Circular flow patterns from drips

Flows create patterns

Mold in wettest area

**The pattern of the stains
suggests multiple
occurrences of
foundation water.**

Black mold

White efflorescence

Liquid flows can make obvious stain patterns.

Water vapor moves with air.

Air flows are more subtle.

To understand water vapor behavior:

Dew Point

Relative humidity (RH)

Condensation occurs at cooler surfaces.



Roof ice patterns from radiational cooling

Clapboard heat loss at studs

**Black
mildew
at the
studs
above...**

**but
absent at
some
studs
below!**



© 2025 J. May

Moisture Content

RH is a measure of how much vapor is in the air compared to the maximum amount of vapor the air can hold at a given temperature.

RH depends on temperature.

If you heat air, the RH decreases.

If you cool air, the RH increases.

Measuring RH

Digital
Thermo-hygrometer

Try
Fluke 971

Inexpensive
instruments are very
inaccurate.




Fluke 971: RH,T, dew point

There is a relationship between the relative humidity (RH) of the air and the moisture content (MC) of materials.

Surfaces are in equilibrium with the relative humidity.

Relative humidity $\div 5 \sim$ EMC



Measuring Moisture Content (MC) of Wood

Types of meters:

Electrical resistance

Electrical impedance

Radio-frequency absorbance

Pin probe Meter

Measures electrical resistance

“Calibrate” with finger check

Short probe, shallow penetration

Metal conducts so looks wet!

Salts conduct so look wet!: fire retardant salts salty ocean spray

The Moisture Content of Wood



Pin probe

Long probe
Penetration
Probe insulation

Wall cavity MC
Side of work box
Move in slowly
Fiberglass
Sheathing back

Aluminum VB
Salts:
Cellulose insulation



Measures impedance

Conducting carbon pads


Quantitative for wood:
% MC

Drawback:

Can't measure narrow spaces

Tips:

Hand test before/after



Three scales:


Quantitative for wood:

% MC

Qualitative for other

Drywall/roofing is most sensitive

Plaster/brick is least sensitive



Tramex moisture encounter

Test in a thick book:

detecting wet paper towel
detecting aluminum foil

**Salts, metals conduct
so appear to be wet**

**OK for asphalt shingles
but not membrane
roofing**



Tramex moisture encounter

Is Ice Wet??

May Indoor Air Investigations


NO!!!

To test moisture content of exterior wood in winter, wood must be above freezing.

Frozen, water-logged wood is dry!

CASE STUDIES

**Water leaks and water vapor
cause rot, mold, rust and
paint peeling.**



**The
homeowner
called the paint
contractor
back.**

**Painter blames
shower moisture!**

© 2025 J. May

**There was a new
roof and a year-
old coat of paint.**

**What was
causing the
blisters?**




May Indoor Air Investigations

Crack at Top of Chimney



A water-filled blister appeared in the front of the stucco.



Back of house with first-time water entry



© 2025 J. May

May Indoor Air Investigations

**Wet wallpaper
1st flr DR**




**Water on floor
2nd flr under window**



Water exited the light fixture

Was bay roof leaking?



Debris in window



Moisture in window

© 2025 J. May



Gutter above window overflowed in heavy rain



My drip edge to keep water away from doorway during heavy rain/overflow



Clogged gutter



Fifteen years of Gutter Neglect in PA

Builder was sued in court



**Above:
the
decayed
sheathing
was under
the
siding.**

**Remind your clients to
keep their gutters and
downspouts clean.**

The Window That Wouldn't Stop Leaking



© 2025 J. May


Note the caulk around the trim
of this northeast-facing window.




Inside, the wallpaper under the window was all stained from the leaks.

May Indoor Air Investigations

Wind-blown rain flowed down the window. .



Water entry at leaky joint



Visible and Concealed Wall Decay



© 2025 J. May

At the home above, pests and both insect and wood decay led to powerful, musty indoor odors. Water entered the wall between the separate window units.



© 2025 J. May

The Leaky Wall that Damaged Newly Finished Oak





There was a long crack in the mortar joint a few courses above the window.

Leaky Wall

It only took a few ounces of water.

© 2025 J. May


Dripping water



Design Flaws and Construction Defects

Lead to the growth of fungi:

Macrofungi
and
Microfungi




Mushrooms are “macrofungi” because the fruiting body is visible.

Need wet conditions and temperature above 55°F to grow

Microfungi (molds) have microscopic fruiting bodies called conidiophores.

The fruiting bodies (conidiophores) of microfungi may be colored, but the structures are too small to be seen by eye.



Microfungi

Cladosporium
mold on a
basement door.

Above: *Aspergillus* mold on the front door of a split-level home.



© 2025 J. May

Is There A Design Problem Here?



© 2025 J. May



Is There A Design Problem Here?

© 2025 J. May

Warped oak

Living room

Stained carpet in baby's room

© 2025 J. May

Baby with respiratory issues removed from room

Is There a Design Problem Here?

Stain

Basement

May Indoor Air Investigations

Is There a Design Problem Here?



**Wet insulation
and OSB in
second-floor
baby's room in
corner of house**

Home with Bad Siding Installation

No flashing strips under clapboard joints

Nails driven in too far


Exposed wood grain at nail depressions not painted

Leak Test at Clapboard Joint

Unfilled nail heads, too deeply set; fibers take in water also!

The resulted was wet sheathing. . .

Flash under clapboard joints!



© 2025 J. May

Northeast-facing Bedroom Wall

Northeast-facing Bedroom Wall

All the interior drywall was removed.



© 2025 J. May

Both macrofungi and microfungi were growing on the OSB. The fungal growth-pattern suggests that water entered the wall from the exterior at the studs (nails and joints) and the window jamb joints.



May Indoor Air Investigations

A Bedroom Odor Complaint Due to Concealed Wall Decay



Bedroom

**No gutters or kick-out flashing
Minimal soffit overhang**

At the:

Concealed Wall Decay




**Return sloped
improperly at
bottom edge**

**Visibly decayed
clapboards**



Concealed Wall Decay



- Window-pitch effect on flow
- Staining at nail penetrations

Concealed Wall Decay



Water flows by capillary action behind OSB at joint.



**White hyphae
delineate flow.**

**Concealed
Wall Decay**

At the .

01/08/2010 PM 06:15

Concealed Wall Decay

May Indoor Air Investigations

Build with ample overhangs

Gutters

Kick-out flashings

Don't set nails in too deeply

House with very musty entry hall but no visible mold


No gutter above entry balcony



© 2025 J. May



Brick veneer



May Indoor Air Investigations LLC

House with very musty entry hall

**No interior stains!!!
No visible mold**

Drywall over front door stunk!



House with very musty entry hall

Elevated moisture content in drywall under 2nd floor window over entry



No odor at 2nd floor over entry!!

© 2025 J. May

Small gap in caulk under window



Remediation of house with very musty entry hall

Front door



Basement



Remediation of house with very musty entry hall



Gulf-Coast House Completely Re-sided



No roof overhang or gutters!



Decayed sheathing

May Indoor Air Investigations

Gulf-Coast House Completely Re-sided



This house must have overhang or gutters!



© 2025 J. May


May Indoor Air Investigations



Above rear deck

Discoloration due to cedar extractive stains is characteristic of water entry behind the clapboards.

Great Design... A Two Year-old House with a Serious Decay Problem




Below rear deck



Great Design...
Gutters at different
levels met at a corner
under a roof valley.
Neither collected the
valley water.

May Indoor Air Investigations

Siding removed beneath the deck



Foundation

**The OSB sheathing
was rotted by decay
fungi and there was
mold growing on the
housewrap.**

A Two Year-old House with a Serious Decay Problem

Siding removed above the
deck

© 2025 J. May



May Indoor Air Investigations

There were basement-ceiling stains in the corner.



A ceiling tile was removed. The framing and back of the OSB were covered with white hyphae from macrofungi. Green microfungal growth was also present.

A Two Year-old House with a Serious Decay Problem

© 2025 J. May


Wood-decay fungi



May Indoor Air Investigations

This condo was on the cover of “Architecture Magazine” . . .

**No caulk or
flashing
at half-round
trim**



. . . for its award-winning soffit design!


Year 1



Year 2



Eight years after construction, all the siding was replaced.



Originally, there was no flashing or caulk at the half-round trim beneath the soffit, which shed roof water down the concave curve and into the wall.

Grade surfaces so that water flows away from the foundation.

Roof water flowed into the 1/8th inch crack between the asphalt and concrete,



The most common causes of excess basement water are poor dispersal of roof water and improper grading.



Excess humidity is a frequent cause of mildew and odors.

May Indoor Air Investigations

Conspiracy Design...



Portabella By-the-Sea:

A four-unit condo complex on the North Carolina Coast




© 2025 J. May

Mushroom at a three year-old building



Portabella By-the-Sea



The severe decay at the three year-old building was due to water penetration at a joint and a lack of flashing at the deck ledge.

© 2025 J. May

Drip Caps Should Be Bent Down!!!!


NOT UP!!!!



Water entered at open mitered joint

© 2025 J. May

Water soaks up the back of the clapboard and runs to the ends of the flashing, and in this case, into the mitered joints, and down the wall behind the trim.





Water from the drip-cap test came out of the wall!

The end of the exterior for an eight year-old house.



Cedar extractive stains

A puff-ball fungus!



Casing



© 2025 J. May

The decayed casing from the left side of the window was removed.

Even the framing lumber at the side of the window was rotted. The rough window opening was never flashed.



Framing



Water entered at mitered joint

Obscure Moisture and Mold Sources with Significant health Impacts

**Central Air Conditioning
Window Air Conditioners
Humidifiers
Dehumidifiers
Frost-free refrigerators**

Anywhere there is wet dust and air flow!!

**Microorganisms will grow in the dust
and allergens will be aerosolized**

“Symptoms, Sources and Solutions **In 600 Sick Structures”**

(Part II of “Sampling, Results & Remediation in 300 ‘Sick Homes,’”
Bioaerosols, Fungi and Mycotoxins (1999), E. Johanning, ed.)

Reports from 600 “sick house syndrome” (SHS) homes were compared to randomly selected reports from 300 homes inspected as part of pre-purchase agreements.

“Symptoms, Sources and Solutions **In 600 Sick Structures”**

In Boston area:

- 19% of homes have central A/C
- 38% of SHS homes have central A/C

**Conclusion: You are twice as likely to have
SHS if you have central A/C**

Many studies have shown a correlation between SBS and Central Air Conditioning

Mold contamination and air handling units. *J Occup Environ Hyg.* 2007 Jul;4(7):483-91
Wilson SC, Palmatier RN, Andriychuk LA, Martin JM, Jumper CA, Holder HW, Straus DC.

Fungal contamination of air conditioning units in operating theatres in India. *J Hosp Infect.* 2005 May;60(1):81-4. Kelkar U, Bal AM

Aeroallergen sensitization in pediatric allergic rhinitis in Singapore: is air-conditioning a factor in the tropics? *Pediatr Allergy Immunol.* 2004 Aug;15(4):340-3. Kidon MI, See Y, Goh A, Chay OM, Balakrishnan A. Rheumatology, Immunology and Allergy Service, KK Children's Hospital, Singapore.

Upper respiratory symptoms associated with aging of the ventilation system in artificially ventilated offices in São Paulo, Brazil. *Chest.* 2002 Aug;122(2):729-35. Gaudenz GS, Kalil et al.

Association of air-conditioning with respiratory symptoms in office workers in tropical climate. *Indoor Air.* 2005 Feb;15(1):62-6. Gaudenz GS, Oliveira CH, Tribess A, Mendes C Jr, Latorre MR, Kalil J.,

Relationships between air conditioning, airborne microorganisms and health | *Bull Acad Natl Med.* 1999;183(2):327-42; discussion 342-4. Parat S, Perdrix A, Baconnier P.

Heterotrophic bacteria in an air-handling system *Appl Environ Microbiol.* 1992 Dec;58(12):3914-20.. Hugenholtz P, Fuerst JA. Department of Microbiology, University of Queensland, Brisbane, Australia.

Mold contamination of automobile air conditioner systems. *Ann Allergy.* 1990 Feb;64(2 Pt 1):174-7. Kumar P, Lopez M, Fan W, Cambre K, Elston RC. Department of Medicine, Louisiana State University Medical Center, New Orleans.


“Symptoms, Sources and Solutions In 600 Sick Structures”

81% had elevated levels of airborne spores

Most common genera found included

Cladosporium
Aspergillus
Penicillium

Examples of moldy condensing equipment



Moldy central A/C coil

Moldy wall-mounted heat-pump return



Moldy window A/C supply



Moldy dehumidifier

Microbial growth on coils and fibrous liners is a leading cause of sick building syndrome (SBS)

Contaminated HVAC systems can cause allergies, asthma and even life-threatening illnesses like hypersensitivity pneumonitis

**Wet materials can be the source of allergenic
fungal spores**

**Sources can include HAVC systems
and wet building materials**

**Spores from decay fungi (macrofungi)
and molds (microfungi) in wall cavities
do not necessarily cause indoor
spore exposures**



2ND EDITION

MY HOUSE IS KILLING ME!

A COMPLETE GUIDE TO
A HEALTHIER INDOOR
ENVIRONMENT

JEFFREY C. MAY AND CONNIE L. MAY


FOREWORD BY JOHANNA M. SAMET, MD
AND ELIZABETH MATSUI, MD, MHS



2020
Second edition

Request quarterly newsletter
from website


May Indoor Air Investigations, Tyngsborough, MA 2006
<www.MayIndoorAir.com>
<www.MyHouseIsKillingMe.com>



2001



2004



2008

Questions??

jeff@mayindoorair.com